



Air
Controls
Products

Service Bulletin Important TPMS Recalls



Vehicles: 2014-2015 Mazda MAZDA6

NHTSA #: 14V675000

Problem: Indirect TPMS software cannot inform driver if all tire pressures drop the same level at the same time.

Solution: Dealership must update Indirect TPMS software.

Vehicle: 2014 RAM ProMaster

NHTSA #: 14V633000

Problem: Receiver could illuminate the wrong location of a low tire.

Solution: Dealership must update TPMS module software.



Vehicles: 2013-2014 Land Rover LR4, 2014 Range Rover, 2014 Range Rover Sport

NHTSA #: 14V618000

Problem: OE sensors won't register to the vehicle.

Solution: Dealership must update TPMS receiver software on all models. In addition to updating, the 2013 LR4 will receive all new sensors.

Vehicles: 2012-2013 Volkswagen CC

NHTSA #: 10051380

Problem: OE sensors won't register to the vehicle.

Solution: Dealership must replace sensors with updated version.



Vehicles: 2014 Dodge Grand Caravan, 2014 Chrysler Town & Country, 2014 Jeep Wrangler

NHTSA #: 14V632000

Problem: TPMS receiver may be in incorrect mode therefore the TPMS light will stay illuminated.

Solution: Dealership must change the receiver's mode.

Vehicle: 2014 Honda Civic

NHTSA #: 10055974

Problem: TPMS light illuminates when pressures are correct.

Solution: Dealership must update Indirect TPMS software.

Dill Air Controls Products 1-800-815-DILL (3455)

www.dillvalves.com