



**Vehicle:** 2016 Honda Pilot

**NHTSA #:** 15V668000

**Problem:** TPMS warning lights may not illuminate if there is a problem unless the vehicle is restarted.

**Solution:** Dealership will update the vehicle's combination meter software.

**Vehicle:** 2015 Honda CR-V

**Honda SB #:** 14-065

**Problem:** TPMS warning light is illuminated and DTC C0077 or C0078 is present yet the tire pressures are correct.

**Solution:** Dealership will update the vehicle's VSA control unit software.



**Vehicle:** 2016 KIA Optima & Sorento

**KIA #:** SA213

**Problem:** TPMS malfunction light flashes at start-up and DTC's are present yet the tire pressures are correct.

**Solution:** Dealership will replace the sensors.

**Vehicle:** 2015-2016 Fiat 500

**Chrysler #:** 08-122-15

**Problem:** TPMS light is illuminated along with DTC's C1012-88 and/or C1015-88 are present.

**Solution:** Dealership needs to reset the system.



### Noncompliance Notice

**Vehicles:** 2007-2009 Ferrari F430, 2012-2014 Lamborghini Aventador, 2008-2010 Murciélago, 2008-2014 Gallardo

**Problem:** Once a TPMS malfunction is detected the TPMS light flashes for at least 60 seconds, but if the ignition is cycled (engine off, engine on), the TPMS malfunction light will not come back on until the vehicle is driven above 23mph for more than 40 seconds.

**Violates:** Paragraph S4.4(c)(2) of FMVSS No. 138 which states the TPMS malfunction light must flash for at least 60 seconds at start-up until the malfunction is corrected.



Dill Air Controls Products 1-800-815-DILL (3455)

[www.dillvalves.com](http://www.dillvalves.com)